


**Ho Sin Hang Campus – Repair Works to External Wall of Corridor from
Levels 6 to 12 of Oen Hall Building**

善衡校園 – 溫仁才大樓六至十二樓走廊外牆維修工程



--- Scaffolding area 6/F – 12/F